

DLE EC7.5 Release for 2012 Products

[Audience](#)

[Supported Products](#)

[Firmware Availability:](#)

[DLE Specific-changes:](#)

[DLE EC7 Upgrade Process](#)

Audience

This document is intended for 'Lexmark and Partners' only.

Supported Products

Models	IPDS Card	FMBC Card	Prescribe Card
MS812	✓	✓	✓
MS811	✓	✓	✓
MS810	✓	✓	✓
MS711	✓	✓	✓
MS710	✓	✓	✓
MS810de	✓	✓	✓
MS812de	✓	✓	✓
MX812	✓	✓	✓
MX811	✓	✓	✓
MX810	✓	✓	✓
MX711	✓	✓	✓
MX710	✓	✓	✓
MS610de	✓	✓	✓
MS610dn	✓	✓	✓
MS510dn	✓	✓	✓
MX611dhe	✓	✓	✓
MX611de	✓	✓	✓
MX610de	✓	✓	✓

MX511dhe	✓	✓	✓
MX511de	✓	✓	✓
MX510de	✓	✓	✓
MX410de	✓	✓	✓
MX310	✗	✗	✗
MS910	✓	✓	✓
MX910	✓	✓	✓
MX911	✓	✓	✓
MX912	✓	✓	✓
CS510de	✗	✓	✓
CS510e	✗	✓	✓
CS410dn	✗	✓	✓
CS410n	✗	✓	✓
CX510de	✗	✓	✓
CX410de	✗	✓	✓
CX410e	✗	✓	✓
CX310dn	✗	✓	✓
CX310n	✗	✓	✓
MX6500e	✗	✓	✓

Firmware Availability:

DLE	Printer	Code Level
IPDS	MS810, MS811, MS812, MS710, MS711	LW75.DN2.P043/IPDS 5.00-01054
	MS810e	LW75.DN4.P043/IPDS 5.00-01054
	MS812e	LW75.DN7.P043/IPDS 5.00-01054
	MX810, MX811, MX812, MX710, MX711	LW75.TU.P043/IPDS 5.00-01054
	MS510dn, MS610dn	LW75.PR2.P043/IPDS 5.00-01054

	MS610de	LW75.PR4.P043/IPDS 5.00-01054
	MX611dhe, MX611de, MX610de	LW75.SB7.P043/IPDS 5.00-01054
	MX511dhe, MX511de, MX510de, MX410de	LW745.SB4.P043/IPDS 5.00-01054
	MS910	LW75.SA.P043/IPDS 5.00-01054
	MX910, MX911, MX912	LW75.MG.P043/IPDS 5.00-01054
FMBC	MS810, MS811, MS812, MS710, MS711	LW75.DN2.P043
	MS810e	LW75.DN4.P043
	MS812e	LW75.DN7.P043
	MX810, MX811, MX812, MX710, MX711	LW75.TU.P043
	MS510dn, MS610dn	LW75.PR2.P043
	MS610de	LW75.PR4.P043
	MX611dhe, MX611de, MX610de	LW75.SB7.P043
	MX511dhe, MX511de, MX510de, MX410de	LW75.SB4.P043
	MS910	LW75.SA.P043
	MX910, MX911, MX912	LW75.MG.P043
	CS410dn, CS410n	LW75.VY2.P043
	CS510de, CS510e	LW75.VY4.P043
	CX310dn, CX310n	LW75.GM2.P043
	CX410de, CX410e	LW75.GM4.P043
	CX510de	LW75.GM7.P043
	MX6500e	LW75.JD.P043
Prescribe	MS810, MS811, MS812, MS710, MS711	LW75.DN2.P043

	MS810e	LW75.DN4.P043
	MS812e	LW75.DN7.P043
	MX810, MX811, MX812, MX710, MX711	LW75.TU.P043
	MS510dn, MS610dn	LW75.PR2.P043
	MS610de	LW75.PR4.P043
	MX611dhe, MX611de, MX610de	LW75.SB7.P043
	MX511dhe, MX511de, MX510de, MX410de	LW75.SB4.P043
	MS910	LW75.SA.P043
	MX910, MX911, MX912	LW75.MG.P043
	CS410dn, CS410n	LW75.VY2.P043
	CS510de, CS510e	LW75.VY4.P043
	CX310dn, CX310n	LW75.GM2.P043
	CX410de, CX410e	LW75.GM4.P043
	CX510de	LW75.GM7.P043
	MX6500e	LW75.JD.P043

DLE Specific-changes:

- No functional enhancements.

DLE EC7 Upgrade Process

Since DLE builds cannot be bundled with engine firmware, the following instructions will update the DLE, RIP, and engine firmware levels to EC7.5 without removing the DLE card.

1. On a DLE printer with lower code level, upgrade the DLE card first by sending the EC7.5 DLE firmware file: LW75.xx.P043.fullfmbc.flr, LW75.xx.P043.fullpre.flr, or LW75.xx.P043.IPDS01054.fullipds5e.flr
2. The printer will automatically reboot after the DLE firmware update is completed.
3. Send the bundled EC7.5 RIP and engine firmware using the modified file:

LW75.xx.P043.FDN.xx.E732.onboard.flis or

LW75.xx.P043.FDN.xx.E715.onboard.flis

4. The printer will automatically reboot after the firmware update is completed.
5. Once the printer is in ready state, verify that the printer is in EC7.5 code level by checking the base, engine and DLE level on "Reports" > "Printer Information".